Sheet1

Recharge Test Data Record

Core Boring Number CB-RS-XX-3

Date Of Test 11-12-99

Test Performed by Nathan Bryan / Kwabena Ofori-Awuah

Ground Water Level 3' 11.5"

Casing Size 3-in

Casing Depth 90 ft. bgs

Hole Diameter at point of test 3.5/8"

				A	B		C	D	E	F
From Depth Elevation	To Depth Elevation	Time Start	Time Stop	Total Time	Depth to Ground Water before test	Depth to Ground Water after test	Stickup above Ground	Total Head	Total Water Injected	Gallons Per Minute
Feet (bgs)	Feet (bgs)	Min	Min	Min	Feet (bgs)	Feet (bgs)	Feet	Feet B+C	Gal	GPM E/A
90.0	95.0	0	5.0	5.0	3'11.5"	3'11.5"	5.0	8'11.5"	685	13.7

NOTES: 1. Record water take with the water maintained at the top of casing.
2. Water depth must be measured immediately before the recharge test.
3. Water depth shall be recorded after test, and noted if changed.
4. Typical test time is 5 minutes.

Note: The recharge test was in accordance w/ CESF delivery order dated 29 October 1999. See note @ bottom of order.

ENC-4

NOV 12 1999 11:08 FR LAW-MIAMI 305 826 1759 TO RSRESTOS P.06/06

Hole No. CB-BS-XX-3

DRILLING LOG | Division SAD | Installation Jacksonville, District | Sheet 1 of 4 sheets

Project: North Lake Belt Transportation Area

Location: C-9 Canal (1.5 mile from US 27)

Drilling Agency: U.S. Drilling

Hole No.: CB-BS-XX-3

Name of Driller: J.C. Moffett

Direction of Hole: ☒ Vertical ☐ Inclined ____ deg. from vert.

Thickness of Overburden: 22 ft

Depth Drilled into Rock: 33 ft (seeleg)

Total Depth of Hole: 95 ft

Size and Type of Bit: 2.88" bit - 3" Casing

Type Drilling Machine: CME-55 Truck Mounted

Total Core Boxes: 11 | Others: 0

Elevation Ground Water: 3' 0"

Date Hole: Started 11-10-99 | Completed 11-11-99

Elevation Top of Hole:

Total Core Recovery for Boring: 61

Signature of Inspector: Mark H. Bray

Elevation	Depth	Legend	Classification of Soil and Rock	% Core Recovery	Sample No.	Remarks
	1.5		LIMESTONE, incompetent moderately hard to hard, porous			
	2.0		REC = 17"/28"			
	4.5		RQD = 0			
	6.0		REC = 30"/63"			
	7.5		RQD = 0			
	9.0		moderately hard to hard, porous, dark brown organic clay inserts between 8'-9' bgs. (3"-6")			
	10.5		competent.			
	12.0		REC = 32"/67"			
	13.5		RQD = 0			
	15.0		moderately hard to hard, competent, slightly porous.			
	16.5		SILT, light grey, sandy, med to coarse limestone fragments (4")			
	18.0		LIMESTONE, moderately hard to hard, incompetent, sand filled solution holes between 15.5'-17.5' bgs. (white silty sand = 4")			
	19.5		REC = 22"/37"			
	21.0		RQD = 0			
			SILT, dark grey, clayey (4")			
			LIMESTONE, hard to very hard, porous.			
			REC = 13"/22"			
			RQD = 9"/15"			
			(continued)			

Casing

0-1 - 0.05"
1-2 - 0.05"
2-3 - 0.05"
3-4 - 0.05"
4-5 - 0.05"
5' of 3" ϕ casing installed.
5-6 - 2.3m"
6-7 - 2.25"
7-8 - 2.31"
8-9 - 2.23"
8' of 3" ϕ casing installed.
9-10 - 2.22"
10-11 - 0.15"
11-12 - 16.12"
12-13 - 1.55"
12' of 3" ϕ casing installed.
13-14 - 0.02"
14-15 - 0.02"
15-16 - 0.02"
16-17 - 0.02"
17-18 - 0.03"
18' of 3" ϕ casing installed.
18-19 - 0.04"
19-20 - 0.04"
20-21 - 0.04"

1.5 — Circulation lost @ 10' bgs. Casing installed to prevent water loss.

9.0 — Boring caved 1-ft between 8'-9' bgs.

12.5 — Possible rock wedged @ bit.

DRILLING LOG (Cont Sheet) Hole No. CB-RS-XX-3

North Lake Belt Impoundment Area — Jacksonville District — Sheet 3 of 4 sheets

Elevation	Depth	Legend	Classification of materials	% Core Recovery	RQD of Rock Core	Remarks
48.0			LIMESTONE			48.0
48.5			REC=28/47"			48.5 still loosing circulation
			RQD=6/10"			49.5
51.0						51.0
52.5						52.5 11-11-99
			REC = 38"/63			54.0
55			RQD= 10"/16			55.5
			competent, porous			
57.0						57.0
58.5			REC= 20"/33			58.5
60.0			RQD= 0%			60.0
			incompetent, porous			
61.5						61.5
63.0			REC= 41"/68			63.0
64.5			RQD= 12"/20			64.5
			few sand filled solution			
66.0			holes, grey-silty.			66.0
67.5						67.5
69.0			REC= 41"/68			69.0
			RQD=22"/37			
70.5			competent, porous			70.5
72.0						72.0
73.5			SAND, no recovery, probable			73.5 coring, no actual recovery of sand. Washed from core barrel. (73'-78')
			same as 78'-79.5'. gravel			
75.0			size limestone fragments recovered.			75.0
			REC= 5"/5			
76.5			RQD= 0			76.5

48' of 3" Casing installed.

53' of 3" Casing installed.

58' of 3" Casing installed.

63' of 3" Casing installed

68' of 3" Casing installed.

53-54 - 0.12"
54-55 - 0.36"
55-56 - 0.09"
56-57 - 0.10"
57-58 - 0.59"

58-59 - 0.14"
59-60 - 0.18"
60-61 - 0.06"
61-62 - 0.13"
62-63 - 0.09"

63-64 - 0.03"
64-65 - 0.25"
65-66 - 1.93"
66-67 - 1.15"
67-68 - 3.30"

68-69 - 0.58"
69-70 - 1.13"
70-71 - 1.44"
71-72 - 0.18"
72-73 - 0.13"

73-74 - 0.06"
74-75 - 0.10"
75-76 - 0.10"
76-77 - 0.16"

ENG FORM 1836-A

N. Lake Belt Impoundment Area CB-RS-XX-3

DRILLING LOG (Cont Sheet)

N. Lake Belt Impoundment Area — Darlington Ville District — Hole No. CB-RS-XX-3

Elevation	Depth	Legend	Classification of Material	% Core Recovery	Run or Sample No.	Remarks	Blow counts
77.0	0		- see previous description			77-78 = 0.09"	77.0
76.5	0.5		SAND, white, grey, some silt, gravel size limestone fragments (SM).	18" / 100	1		78.5
80.0	3.0			18" / 100	2		80.0
81.5	4.5			18" / 100	3		81.5
83.0	6.0			18" / 100	4		83.0
84.5	7.5		Transition zone from sand to silt.	18" / 100	5		84.5
86.0	9.0		SILT, little fine to medium sand, dark grey, clayey	18" / 100	6	last 2" of spoon was SILT.	86.0
87.5	10.5			18" / 100	7		87.5
89.0	12.0		SILT, grey, sandy - medium to course.	17" / 94	8		89.0
90.5	13.5		SILT, trace medium to course sand, clayey, grey.	18" / 100	9	Recharge test from 90'-93' bgs.	90.5
92.0	15.0			18" / 100	10		92.0
93.5	16.5			18" / 100	11	2-ft spoon from 93'-95'	93.5
95.0	18.0						95.0

Boring Terminated @ 95' bgs.

Note: Boring offset ≈ 10-ft from original location due to track rig being vandalized. Possible metal objects in hole.

ENG FORM 1836-A (MAR 1988) EP 1110-1-1000

N. Lake Belt Impoundment Area — CB-RS-XX-3